

SINGAPORE OFFICE
BLK 511, KAMPONG BAHRU ROAD
#05-04 KEPPEL DISTRI PARK
SINGAPORE 089447
TEL : 65-62731411
FAX : 65-62786624
UEN : S71FC2158K
URL <http://www.nkkk.jp/>
HEAD OFFICE : TOKYO
BRANCHES
ALL PRINCIPAL PORTS IN JAPAN
OVERSEAS OFFICES
THAILAND, MALAYSIA, PHILIPPINES,
INDONESIA, CHINA, NETHERLANDS,
VIETNAM, HONG KONG, TAIWAN
LABORATORIES
YOKOHAMA, OSAKA



INTERNATIONAL INSPECTION & SURVEYING
INSPECTIONS REQUIRED BY REGULATIONS FOR
DANGEROUS GOODS, SOLID BULK SUBSTANCES AND
NOXIOUS LIQUID SUBSTANCES
MARINE SURVEY AND CARGO INSPECTION
MARINE CONSULTANT
NON-MARINE ADJUSTING
PETRO-CHEMICAL SUPERINTENDING
LIQUEFIED GAS INSPECTION
CHEMICAL ANALYSIS
TANK CALIBRATION
SAMPLING AND TESTING
CARGO WEIGHING AND MEASURING

2nd Draft

(Ref : YON/nu)

SINGAPORE OFFICE
12 January 2015
Cert No. PQ 24/14

INSPECTION CERTIFICATE

THIS IS TO CERTIFY THAT we, the undersigned, did, at the request of

_____ . Ltd.

attend on 8 and 9 January 2015 in order to inspect the under mentioned used machines to be exported to Thailand with respect to its condition, labor safety and health, effect to environment, residual life and value, and hereby report as follows:-

Description : Used machines

Consignee : _____ Component (Thailand) Ltd.
500
Hemaraj Eastern Seaboard
T.Tasit, A. Pluakdaeng, Rayong
Thailand

Shipper : _____ Corporation (S) Pte. Ltd.
50 Science Park Road
#04-04 The Kendall
Singapore Science Park II
Singapore 117406

Delivered to : _____ Component (Thailand) Ltd.
500
Hemaraj Eastern Seaboard
T.Tasit, A. Pluakdaeng, Rayong 21140
Thailand

Quantity : (5) units

Country of Origin : Japan / U.S.A. / Thailand / Singapore / Germany

Inspection Place : Nippon Express (Singapore) Pte. Ltd.
Ocean Cargo Branch
5C Toh Guan Road East
Singapore 608828

List of Used Machines

<u>S/No</u>	<u>Description</u>	<u>Q'ty (unit)</u>	<u>Maker</u>	<u>Country of Origin</u>	<u>Date Manufactured</u>	<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>	<u>Intended Usage</u>
1	Used Ink Jet Printer Machine Model: HSM	1	G-Tech	Singapore	2003	20	11	9	25,938.00	Assembly Line Machine
2	Used Surface Mounter Model: YG100	1	Yamaha	Japan	2006	20	8	12	41,563.00	Assembly Line Machine
3	Used QAG Press Machine Model: FC-459-B Serial No. PEC-06-045	1			2006	20	8	12	4,063.00	Assembly Line Machine
4	Used DI Water Cleaning Machine Model: CBW-224	1	Stoelting	USA	2003	20	11	9	114,063.00	Assembly Line Machine
5	Used X-Ray Machine Model: Phoenix	1	Keteca	Germany	2003	20	11	9	15,625.00	Assembly Line Machine

A) Designed Working Life (year)

B) Total Working Life Past (year)

C) Balance Years of Usage (year)

D) Booking Value (US\$)

Particular of used machines

<u>No.</u>	<u>Description</u>	<u>Q'ty (unit)</u>	<u>Value (US\$)</u>
1.	Used Ink Jet Printer Machine Model: HSM	1	25,938.00
2.	Used Surface Mounter Model: YG100	1	41,563.00
3.	Used QAG Press Machine (Depanalizer) Model: FC-459-B, Serial No. PEC-06-045	1	4,063.00
4.	Used DI Water Cleaning Machine Model: CBW-224	1	114,063.00
5.	Used X-Ray Machine Model: Phoenix	1	15,625.00
Total:		<u>5 units</u>	<u>US\$ 201,252.00</u>

Inspection

The quantity, external condition, care for labor safety and health and effect to environment of the used machines were inspected, and its residual life and value were appraised by assessing the relevant documents submitted by the applicant, and the results were as follows: -

1. Quantity

The quantity of the used machines was in conformity to the description on the "List of Used Machines" as per attachment.

2. External Condition

The machines were used, but well maintained without any noticeable defect and in apparently serviceable condition.

3. Labor safety and hygiene

The used machines had sufficient hygiene and labor safety functions against any risk or accident.

4. Effect to environment

The operation of the said used machines would have no influence on the environment pollution.

5. Residual Life

The residual life of the used machines was investigated by evaluating its age, working periods and maintenance. The residual life of the used machines was appraised to be at least 9 years, provided that it is operating under normal condition with adequate maintenance and control.

6. Valuation

The value of the used machines was appraised by taking into account the manufacturer date, present conditions, and maintenance, etc. as shown in the attached "List of Used Machines" which was considered reasonable.

This report has been carried out to the best of our knowledge and ability, and our responsibility is limited to the exercise of reasonable care and this certificate is not intended to relieve sellers from their contractual obligations.

NIPPON KAIJI KENTEI KYOKAI
SINGAPORE OFFICE

T. IKEHARA, GENERAL MANAGER